

## CT 21 gallon 110 Dry Applicator

## 21 Gallon





## **HOW IT WORKS**

The CT Applicator brush pushes the powder through a mesh. This sifts the powder into small particles, resulting in proper distribution. Quantities can be easily and accurately adjusted by changing the speed of the brush rotation.